








GP042-0019,1


















The necessary tools (not included)


ACCESSORY LIST

A01  20x	A02  20x	A03  20x	A04  A 16x D-1 2x D-2 2x	A12  6x DM
A13  6x MA	A50  8x M6X15	A26  1x 5mm	A10  32x 3,5x18	A14  2x M4x22
A28  30x	C62  1x (SYH)	B90  2x DKR-058 H444 MTL (Texture Syh)	0x	0x


GENERAL VIEW




1




2




3




4




5





6



7



8



9

