



GP042-0064,1








The necessary tools (not included)


ACCESSORY LIST


A09 8x	A02 32x	A01 40x	A03 24x	A44 4x
A10 36x	A11 4x	A13 4x	A64 2x	A14 4x
A95 5x	A28 20x	A04 A 32x	A16 A 8x	

GENERAL VIEW






1









3






4









6



7





8




9

9




10





10


11







12


















The necessary tools (not included)


ACCESSORY LIST

A09  4x50 15x	A08  Ø8 3x	A16  A 15x
---	--	---

GENERAL VIEW



1



2

