














GP042-0302,1







| | | | | |
|--|---|---|--|--|
| A01  44x | A02  32x | A03  3x | A09 4x50 YHB  4x | A04  A 24x D2 20x |
| G94  Ø14 BYZ 4x | A44  6x | A16  D2 4x | | |




4




5




6




7




8



9



10



TWO PEOPLE ARE REQUIRED TO
MOVE AND ASSEMBLE THIS MODULE

