






**GP042-0005,2**













The necessary tools (not included)


## ACCESSORY LIST

A02  20x	A01  20x	A03  20x	A12  4x	A13  4x
A10  3,5x18 32x	A09  4x50 11x	A64  2x	A14  M4x22 4x	A67  1x
A29  3,5x30 4x	A08  3x	A04  A 20x	A16  A 11x	B49  2x
B50  2x	A28  20x			




## GENERAL VIEW







1




2




3







4




5



6




7




7


8



A09




9



A10

B50

10



A16

