








GP042-0156,1











The necessary tools (not included)









ACCESSORY LIST

A12 4x	A13 4x	A09 4x50 15x	A10 3,5x18 44x	A08 4x
A16 A 12x	A28 20x	A35 4x	A36 4x	





GENERAL VIEW



1




2




5


3




4




5



6




7








7

8



9



10

