






GP042-0010,1










The necessary tools (not included)


ACCESSORY LIST


A01	A02	A03	A10	3,5x18	C46
59x	51x	28x	16x		2x
A13	A08	A09	A84	M4x26	A28
4x	4x	4x	4x		23x
	A16	A04	A06	A12	
	D 4x		A 55x	4x	
			D 4x		

GENERAL VIEW










1








3










9





10




11






12






13



14



12

