






GP042-0060,1

















The necessary tools (not included)

ACCESSORY LIST


A02  20x	A01  20x	A03  20x	A10  3,5x18 36x	A11  4x
A13  4x	A28  25x	B45  2x	A14  M4x22 8x	B43  20 cm 5x
A04  A 20x				

GENERAL VIEW







2






3




4







5







6





7





















The necessary tools (not included)


ACCESSORY LIST

A02  28x	A01  32x	A03  24x	A10 3,5x18  16x	B46  1x
A14 M4x22  2x	A12  2x	A13  2x	A28  10x	A09 4x50  4x
A23  1x	A08 Ø8  4x	A41  4x	A06  2x	A04  A 32x



GENERAL VIEW






1






2




3



4




5




6





6



7



8



7

