






GP042-0061,1
















The necessary tools (not included)


ACCESSORY LIST

A09  4x50 6x	A66  3,5x40 28x	B10  M6x40 8x	A16  3x	A08  Ø8 3x
B57  DKR-010 H1730 DKR-010 H432 1x				


GENERAL VIEW




1




2





3



4





6

