






GP042-0065,1










The necessary tools (not included)


ACCESSORY LIST

A01 24x	A02 24x	A03 24x	A45 3,5x20 36x	A04 A 24x
A12 2x	A13 4x	A11 2x	B46 1x	A14 2x
A17 1x	C23 (479X50)	A16 A 4x	A09 4X50 4x	A08 4x
A28 30x	B14 1x	A20 3,5x25 3x	A86 4x	A34 2x


GENERAL VIEW




1




2




3




4






5




6







7







8



9



10



11

