

















**GP042-0075,1**



















The necessary tools (not included)


## ACCESSORY LIST

<b>A01</b>  <b>12x</b>	<b>A02</b>  <b>12x</b>	<b>A03</b>  <b>12x</b>	<b>A04</b>  <b>A12x</b> <b>D 0x</b>	<b>B20</b> M6x10 YHB  <b>8x</b>
<b>A38</b> 3,5x35 YHB  <b>12x</b>	<b>C64</b>  <b>1x</b>	<b>C65</b>  <b>1x</b>	<b>D50</b>  <b>1x</b>	


## GENERAL VIEW




1




2






3






4



5



6



7

