













GP037-0002,2



P07  B.A.M 1x	A28  3,5x50 1x	A16  DbØ8 1x
---	--	--

1. step



2^{step}

