




GP037-0006,2




ACCESSORY LIST

P06	C.A.M	A28	3,5x50	A16	DbØ8
1x			2x		2x

1.
step




STEP-1




A28

STEP-3



A16

STEP-2



5mm

2. step

