



i GP100-0069,2



120 x 51,8 x 240cm

1



2







Diagram 2 illustrates the second step of the assembly process. The second panel (labeled 2) is being attached to the first panel (labeled 1). A screwdriver is shown driving a screw into the top edge of the second panel, securing it to the first panel. The diagram shows the alignment of the panels and the placement of the screws.


5




6




7




8




9




10




11




12




13




14











15





16











20




21







1




2




3




4




5




6




7




8




8




9




10



11



12



13

