









GP042-0079,1

















The necessary tools (not included)

ACCESSORY LIST








A02  18x	A01  18x	A03  18x	A09  4x50 6x	A16  A 4x D 2x
A04  A 10x D 8x				

GENERAL VIEW






1




5


2




3





4










5



6



7



8

