









GP042-0110,2










The necessary tools (not included)


ACCESSORY LIST

A09 30x 4x50	A10 16x 3,5x18	A12 4x	A13 4x	A16 A 30x
A28 25x	A23 8x	A62 2x	A01 5x	A02 5x
A03 2x	A04 A 5x			


GENERAL VIEW




1





2




3



4




5




6

6



7



7

8

