






GP042-0114,2











The necessary tools (not included)

ACCESSORY LIST


A01  54x	A02  38x	A03  24x	A29  3,5x30 4x	A04  A 18x D 36x
A16  A 4x	A44  8x			

GENERAL VIEW







2




3





4




5




6**7**



8




9





10



11



12



13

