









GP042-0134,1











The necessary tools (not included)









ACCESSORY LIST

A01 24x	A02 24x	A03 12x	A04 A 24x	A12 2x
A13 2x	A38 3,5x35 8x	A10 3,5x18 8x	B20 M6x10 2x	A09 4x50 8x
A16 A 8x	C07 SYH 1x	C06 M 3,5x30 2x	D14 2x	D15 1x
D48 1x	D45 4x			


GENERAL VIEW






2**3****4****5**


6




7



8



9



10

