






GP042-0188,2










The necessary tools (not included)







ACCESSORY LIST

A01 32x	A02 28x	A03 28x	A10 3,5x18 36x	A14 M4x22 4x
A11 4x	A13 4x	A06 2x	A24 128 mm 2x	A23 2x
C09 15 cm 4x	A04 A 32x	A28 16x		











GENERAL VIEW






1




2






3






4






5






6






7




8



9





10



(10)

11



12

