




GP035-0015,2







USING TOOLS





Tx12	Fx14	Px14	Kx15	Lx1	VLx2	Vx22	Bx13	VPx12
KRx30	Hx1	Mx2	CPx1	Cx1	CSx1	PTx5	Ux1	VUx1





5





6





7





8





9





10





11





12





13





14




15




16






17







PLASTIC COVER CAPS FOR SCREWS















5





6











7





8








13



14



15



PLASTIC COVER CAPS FOR SCREWS

