








GP042-0204,2










The necessary tools (not included)


ACCESSORY LIST


A01 36x M4x22	A02 36x	A03 16x	A10 24x 3,5x18	A28 28x 4x50
A14 6x	A04 A 36x	A16 A 12x	A24 3x	A09 12x
				A78 3x

GENERAL VIEW






1









3



4






5






7


6



7






8






8

9




10



11

12



13

