






GP042-0054,1










The necessary tools (not included)


ACCESSORY LIST


A02  22x	A01  22x	A03  40x	A09 4x50  22x	A10 3,5x18  32x
A04  A 18x D 4x	A16  A 24x	C13  8x		



GENERAL VIEW




1









4




5




6




7



8




9




10

10



11



11

