







GP042-0058,1










The necessary tools (not included)


ACCESSORY LIST

A01 44x	A02 36x	A03 28x	A44 4x	A11 2x
A13 2x	A10 3,5x18 16x	A14 M4x22 2x	A08 Ø8 3x	A09 4x50 15x
B41 1x	C14 20 cm 2x	A16 15x	A04 D 12 A 32x	A28 20x












GENERAL VIEW




1




2




3




4




5







6




7






8




9




10




11




12





13



14



15



16

