






GP042-0136,1










The necessary tools (not included)


ACCESSORY LIST

A02 20x	A01 20x	A03 12x	A09 4x50 YHB 10x	A10 3,5x18 YHB 20x
A28 20x	A85 2x	A14 M4x22 4x	A41 2x	A08 Ø8 2x
A43 30 cm 2x	B14 2x	A04 A 20x	B15 2x	A20 3,5x25 YHB 6x


GENERAL VIEW




1




2




3




4




5




6




7




8




9




10




11





12




13




14



15



16



17

