






GP042-0198,1










The necessary tools (not included)


ACCESSORY LIST

A02 20x	A01 20x	A03 12x	A43 30 cm 2x	A10 3,5x18 YHB 36x
A09 4x50 YHB 10x	A08 Ø8 2x	A64 2x	A41 2x	A14 M4x22 4x
A04 A20x	A28 25x	B16 4x <small>DKR-013 H720</small>	A16 8x	


GENERAL VIEW




1






2




3




4




5




6




7






8




9




10



11



12



13

